

## **Certificate/Report of Evaluation**

Manufacturer: Fluke Model: 77 Series II Description: Multimeter

Serial Number: 63331402
Technician: Stewart M. Robertson
Report Number: 2-63331402

Test Results: Passed

**Date Checked:** 09-12-2002

Due Date: 09-12-2003 Received: In tolerance Returned: In tolerance

## Reference Used

<u>Manufacturer</u>	<u>Model</u>	<b>Description</b>	Cal Date	<u>Due Date</u>
Fluke	45	Multimeter	12-11-2001	12-11-2002

## **Test Data**

Test Points (BAC DataMaster #921012)	<u>Reference</u>	<u>Test Meter</u>	Acceptable Range
TP1 and TP5 (Sample Chamber Board)	$2.40~V_{DC}$	2.400 V <sub>DC</sub>	+/- 0.3% (2.39 – 2.41 V <sub>DC</sub> )
TP0 and TP2 (CPU Board)	$2.00~V_{DC}$	$1.999~V_{DC}$	+/- 0.3% (1.99 - 2.01 V <sub>DC</sub> )
TP4 and bottom of R45 (Detector Board)	$120.0~\mathrm{V_{DC}}$	$120.1~\mathrm{V_{DC}}$	+/- 0.3% (119.6 – 120.4 V <sub>DC</sub> )

Comments: AS FOUND DATA IN TOLERANCE. NO ADJUSTMENT REQUIRED.